



* Primary DC resistance as wired is 5.10
 Secondary DC Resistance for HT is 500 per winding.
 Turns Ratio = 1 : 2.176 (259/119)
 $RT = S_1 + (2.176^2) \times 50 = 590$



PUSHY CROAKER